## ABSTRACT

A method for insulating a bonding wire that includes the steps of attaching a bonding wire to a bond 5 pad and coating the bonding wire with an insulating liquid while drawing the bonding wire through a bond tool from the bond pad to a package lead.